

BMCA Rt 50 Shoulder Beautification and Restoration Project Overview October 2015

Boulevard Manor Neighborhood

Montague Street Bus Stop Area. Needs beautification and improvement of paths, guard rails and bus waiting area. Also, potentially drainage.

Grassy Area. Has grass, a few trees and screening bushes. Needs screening trees/bushes.

Overgrown Area. In poor shape. Needs removal of ivy, trash trees, undergrowth and then replanting. Will be impossible to remove litter without clean up of underbrush.

Manchester Street Intersection. Overgrown and deep drainage ditch at corner which is potentially dangerous. Needs same work as overgrown area and more. Will add on to what WMATA/County does when it fixes up bus stop.



Approximately 1000 Feet

Seven Corners (W)

Washington, DC (E)


Google earth

Imagery Date: 10/13/2012 38°51'59.15" N 77°08'09.77" W elev 278 ft eye alt 1459 ft

Montague Street Bus Stop Area




Montague Street Bus Stop Area



Grassy Area



Overgrown Area



Manchester Street Intersection (NW Corner)



Trees in Spring With Flowers

